

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave.St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.12**DAILY PROJECT JOURNAL****Prime Contractor:** American Bridge/Fluor Enterprises, a JV**Report No:** DPJ-000522**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Dated:** 07-Dec-2007**Location:** Changxing Island, Shanghai, China

**Submittals(New / Total):**      **CWR's:** /      **HSR's:** /      **NCR's:** /

Item	Title	Detail
1	Other important observations	<p>At 1300, I went on a Fabrication Shop Walkthrough. I observed the following:</p> <p>77m Mockup: No work being performed on skin plates. Diaphragm plates are still in Pudong being machined.</p> <p>89m Mockup: ZPMC personnel were performing grinding of plate edges. No welding operations were ongoing on 89m mock up material.</p> <p>114m Mockup: Temporary lifting devices were being welding on the lower section of the mockup. Skin "D" of the 114m upper section still needed to be fit up. Interior splice plate "A" was still in the 80 degree jig, CWR 28 was being finished. The lower section of the mockup did not appear to have had any welding performed on it other the previously applied tack welds.</p>
2	Heat Straightening Requests (HSRs)	I reviewed and approved HSR 022R00.
3	Meetings attended	I attended training on HSR, CWR and Weekly Welding Report review procedures.

**Inspected By:** Ishibashi,Josh

Quality Assurance Inspector

**Reviewed By:** Wahbeh,Mazen

QA Reviewer